



Vac3000



Calibration Kits	Description	Quantity
IS33-36/3000psi	Dual range calibrator 36 & 3000 psi, 0.05% of reading accuracy	1
QTHP-2FBA	5kpsi / 35 MPa Hydraulic hand pump, 2 Quick-test outlet ports, 3 ft hose, 1/4" FNPT gauge conn., 1/4" MNPT Process conn.	1
DPPV-0000	DPPV (+125 psi to -23" Hg) pump, no gauge adapter, with 3ft hose, 1/4" MNPT process connection	1
QTHA-2TBO	Quick-test to 1/4" tube - Brass	1
QTHA-FRSO	Quick-test to DP transmitter adaptor (Rose, Yoko, Fox)	1
QTHA-1MBO	Quick-test to 1/8" npt male - Brass	1
QTHA-2MBO	Quick-test to 1/4" npt male - Brass	1
QTHA-1MBA	1/8" npt male to Quick-test nut - Brass	1
QTHA-2MBA	1/4" npt male to Quick-test nut - Brass	1
UK 718 Case	(17.8 x 12.8 x 6.8") lockable, water tight protective case	1
C1 Soft pouch	Cameron Soft pouch for instruments and fittings	2
Screw Drivers	Cameron Phillips and Blade adjustment tools	1

1-888-863-8010

www.cameroninstruments.com

Calibration Kit cases come with pick and pluck foam that allows you to customize accessories. The pick and pluck foam is easily cut and designed to protect your calibration equipment.



TBO



MBA



FRSO



MBO



1.888.863.8010

www.cameroninstruments.com
info@cameroninstruments.com

Vac3000/5000 Operational Diagram



QTHA-1MBA

1/8"npt male to Quick-test nut

QTHA-1MBO

Quick-test to 1/8"npt male



QTQT-HOS3'
3' microbore hose



QTQT-HOS3'
3' microbore hose

**Optional Fittings:



QTHA-3TBO

Quick-test to 3/8" tube - Brass



QTHA-4TBO

Quick-test to 1/2" tube - Brass



QTHA-2FSO-QD

Quick-test to 1/4"npt female - SS



QTHA-4FSO-QD

Quick-test to 1/2"npt female - SS

*Connection Fittings:



QTHA-FRSO

Quick-test to DP transmitter adaptor
(Rose, Yoko, Fox)



QTHA-2TBO

Quick-test to 1/4" tube - Brass



QTHA-2MBO

Quick-test to 1/4"npt male - Brass